

3M

Scotch-Weld™

Epoxy Adhesive

1751 B/A

Technical Data

October, 2002

Product Description

3M™ Scotch-Weld™ Epoxy Adhesive 1751 B/A is a gray, aluminum filled, two-part, room temperature curing structural adhesive.

Features

- Excellent adhesion to metals
- Good void filling properties
- Ideal for repairing holes, dents and cracks in metal

Typical Uncured Physical Properties

Note: The following technical information and data should be considered representative or typical only and should not be used for specification purposes.

Color	Base (B) Accelerator (A)	Gray Amber
Base	Base (B) Accelerator (A)	Modified Epoxy Modified Epoxy
Net Weight (lbs/gal)	Base (B) Accelerator (A)	10.8 7.9
Viscosity (Approx.) Time to deliver 20 gms @ 50 psi thru a 0.104" orifice	Base (B) Accelerator (A)	145 seconds 125 seconds
Mix Ratio (By Weight)	Base (B) Accelerator (A)	2 parts 1 part
Mix Ratio (By Volume)	Base (B) Accelerator (A)	3 parts 2 parts
Work Life 100 gram Qty. @ 75°F (24°C) (Approx. Time)	Base (B) Accelerator (A)	45 minutes 45 minutes

Scotch-Weld™

Epoxy Adhesive

1751 B/A

Typical Cured Properties

Note: The following technical information and data should be considered representative or typical only and should not be used for specification purposes.

Physical

Color	Gray
Shore D Hardness ASTM D-2240	75-80
Time to Handling Strength at 75°F (24°C)	8-12 hours
Time to Full Cure at 75°F (24°C)	7 days

Thermal

Thermal Conductivity	0.2229 BTU/Hr/Ft ² /°F/Ft @ 96°F (36°C)
----------------------	--

Handling/Curing Information

Directions For Use

1. For high strength structural bonds, paint, oxide films, oils, dust, mold release agents and all other surface contaminants must be completely removed. The amount of surface preparation depends on the required bond strength and the environmental aging resistance desired by user. See surface preparation section.
2. Use gloves to minimize skin contact with adhesive.
3. This product consists of two parts. Mix thoroughly by weight or volume in the proportions specified in the Uncured Properties Section. Mix approximately 15 seconds after a uniform color is obtained.
4. For maximum bond strength, apply product evenly to both surfaces to be joined.
5. Application to the substrates should be made within 45 minutes. Large quantities and/or higher temperatures will reduce this working time.
6. Join the adhesive coated surfaces and allow to cure at 60°F (16°C) or above until firm. Up to 200°F (93°C), will speed curing.
7. The following times and temperatures will result in a full cure:

<u>Cure Temperature</u>	<u>Time</u>
75°F (24°C)	7 days
150°F (67°C)	120 minutes
200°F (93°C)	30 minutes

8. Keep parts from moving until handling strength is reached. Contact pressure is necessary. Maximum shear strength is obtained with a 3-5 mil bond line.

9. Excess uncured adhesive can be cleaned up with ketone type solvents.*

Adhesive coverage: A 0.005 in. thick bondline will yield a coverage of 320 sq. ft./gallon.

***Note:** When using solvents, extinguish all ignition sources and follow manufacturer's precautions and directions for use.

Scotch-Weld™

Epoxy Adhesive

1751 B/A

Application and Equipment Suggestions

These products may be applied by spatula, trowel or flow equipment.

Two-part mixing/proportioning/dispensing equipment is available for intermittent or production line use. These systems are ideal because of their variable shot size and flow rate characteristics and are adaptable to most applications. For more information, contact your local 3M sales representative.

Surface Preparation

For high strength structural bonds, paint, oxide films, oils, dust, mold release agents and all other surface contaminants must be completely removed. The amount of surface preparation depends on the required bond strength and the environmental aging resistance desired by user.

The following cleaning methods are suggested for these common surfaces:

Steel:

1. Wipe free of dust with oil-free solvent such as acetone, isopropyl or alcohol solvents.*
2. Sandblast or abrade using clean fine grit abrasives.
3. Wipe again with solvent to remove loose particles.
4. If a primer is used, it should be applied within 4 hours after surface preparation. If primer such as 3M™ Scotch-Weld™ Structural Adhesive Primer 1945 B/A is used, apply a thin coating (0.5 mils) on the metal surfaces to be bonded, air dry for 10 minutes, then cure for 30 minutes at 180°F (82°C) prior to bonding.

***Note:** Read and follow component supplier's environmental, health and safety recommendations prior to preparing this etch solution.

Aluminum:

1. Vapor Degrease: Perchloroethylene condensing vapors for 5-10 minutes.*
2. Alkaline Degrease: Oakite 164 solution (9-11 oz./gallon water) at 190°F ± 10°F (88°C ± 5°C) for 10-20 minutes. Rinse immediately in large quantities of cold running water.
3. Acid Etch: Place panels in the following solution for 10 minutes at 150°F ± 5°F (66°C ± 3°C).

Sodium Dichromate	4.1-4.9 oz./gallon
Sulfuric Acid, 66°Be	38.5-41.5 oz./gallon
2024-T3 aluminum (dissolved)	0.2 oz./gallon minimum
Tap Water as needed to balance	
4. Rinse: Rinse panels in clean running tap water.
5. Dry: Air dry 15 minutes; force dry 10 minutes at 190°F (88°C) ± 10°F (5°C).
6. If primer is to be used, it should be applied within 4 hours after surface preparation.

Scotch-Weld™

Epoxy Adhesive

1751 B/A

Surface Preparation (continued)

Plastics/Rubber

1. Wipe with isopropyl alcohol.*
2. Abrade using fine grit abrasives.
3. Wipe again with isopropyl alcohol.*

Glass

1. Solvent wipe surface using acetone or methyl ethyl ketone (MEK).*
2. Apply a thin coating (0.0001 in. or less) of primer such as 3M™ Scotch-Weld™ Structural Adhesive Primer EC-3901 to the glass surfaces to be bonded and allow the primer to dry before bonding.

***Note:** When using solvents, extinguish all ignition sources and follow manufacturer's precautions and directions for use.

Typical Adhesive Performance Characteristics

Note: The following technical information and data should be considered representative or typical only and should not be used for specification purposes.

1. Overlap Shear (psi) ASTM D-1002-72

Test Temperature	Aluminum FPL Etch	Steel Solvent Wipe
-67°F (-55°C)	1400	1500
75°F (24°C)	2000	2400
180°F (82°C)	500	200

Overlap Shear Strength (psi) on various substrates.

Steel to Aluminum	2160
Steel to Steel	2440
Steel to Copper	2245
Aluminum to Copper	2570
Maple to Polyester	690

Scotch-Weld™

Epoxy Adhesive

1751 B/A

Typical Adhesive Performance Characteristics (continued)

Note: The following technical information and data should be considered representative or typical only and should not be used for specification purposes.

2. T-Peel Strength (piw) ASTM D-1876-61T

Test Temperature	Aluminum FPL Etch	Steel Solvent Wipe
75°F (24°C)	4	5

3. Environmental Aging

Overlap Shear Strength (psi) after environmental aging, aluminum to aluminum (ASTM D-1002-72).

300°F (149°C) Aged 8 days	Hyd Oil 30 days @ 75°F (24°C)	Tap Water 30 days @ 75°F (24°C)	20% Salt Spray 30 days @ 95°F (35°C)	JP-4 Fuel 30 days @ 75°F (24°C)
2200	2000	2000	2000	2000

Note: All data developed using a 7 day @ 75°F (24°C), 2 psi cure.

Storage

Store products at 60-80°F (15-27°C) for maximum storage life.

Shelf Life

Rotate stock on a “first in-first out” basis. 3M™ Scotch-Weld™ Epoxy Adhesive 1751 B/A has a storage life of two years in unopened containers.

Scotch-Weld™

Epoxy Adhesive

1751 B/A

Precautionary Information

Refer to Product Label and Material Safety Data Sheet for health and safety information before using this product. For additional health and safety information, call 1-800-364-3577 or (651) 737-6501.

For Additional Information

To request additional product information or to arrange for sales assistance, call toll free 1-800-362-3550 or visit www.3M.com/adhesives. Address correspondence to: 3M Industrial Adhesives and Tapes Division, 3M Center, Building 220-7E-01, St. Paul, MN 55144-1000. Our fax number is 651-733-9175. In Canada, phone: 1-800-364-3577. In Puerto Rico, phone: 1-787-750-3000. In Mexico, phone: 52-70-04-00.

Important Notice

3M MAKES NO WARRANTIES, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. User is responsible for determining whether the 3M product is fit for a particular purpose and suitable for user's method of application. Please remember that many factors can affect the use and performance of a 3M product in a particular application. The materials to be bonded with the product, the surface preparation of those materials, the product selected for use, the conditions in which the product is used, and the time and environmental conditions in which the product is expected to perform are among the many factors that can affect the use and performance of a 3M product. Given the variety of factors that can affect the use and performance of a 3M product, some of which are uniquely within the user's knowledge and control, it is essential that the user evaluate the 3M product to determine whether it is fit for a particular purpose and suitable for the user's method of application.

Limitation of Remedies and Liability

If the 3M product is proved to be defective, THE EXCLUSIVE REMEDY, AT 3M'S OPTION, SHALL BE TO REFUND THE PURCHASE PRICE OF OR TO REPAIR OR REPLACE THE DEFECTIVE 3M PRODUCT. 3M shall not otherwise be liable for loss or damages, whether direct, indirect, special, incidental, or consequential, regardless of the legal theory asserted, including, but not limited to, contract, negligence, warranty, or strict liability.

ISO 9002

This Industrial Adhesives and Tapes Division product was manufactured under a 3M quality system registered to ISO 9002 standards.



Industrial Adhesives and Tapes Division

3M Center, Building 220-7E-01
St. Paul, MN 55144-1000



Recycled Paper
40% pre-consumer
10% post-consumer

Printed in U.S.A.
©3M 2002 78-6900-9909-4 (10/02)