



LOCTITE® 7214™

August 2007

PRODUCT DESCRIPTION

LOCTITE® 7214™ provides the following product characteristics:

Technology	Epoxy
Appearance (Mixed)	Grey
Chemical Type	Epoxy
Components	Two component - requires mixing
Cure	Room temperature cure
Application	Surface preparation
Specific Benefit	• Superior resistance to chemicals and wear • Does not require induction time • Enhances adhesion properties to metal surfaces • Reduces corrosion to metal surfaces

LOCTITE® 7214™ is a two-component, epoxy-polyamide primer under typical dry service temperatures of -29 °C to +60 °C. It is recommended for increasing adhesion of Big Foot™ Flooring Products (anti-slip coatings) on metal surfaces, and for reducing corrosion on metal surfaces. LOCTITE® 7214™ is designed to be used in conjunction with Big Foot™ Flooring Products.

TYPICAL PROPERTIES OF UNCURED MATERIAL

Mixed:

Specific Gravity @ 25 °C	1.45
Total Volatile Content, ASTM D 2369, %	35
Volume of Solids, %	64
Coverage	26 m² per 3.8 liter kit
Weight Per Gallon, lbs/gal	13.1 to 13.6 ^{LMS}
Viscosity @ 25°C, mPa·s (cP)	1,800 to 2,500 ^{LMS}
Flash Point - See MSDS	

TYPICAL CURING PERFORMANCE

Curing Properties

Drying Time @ 25 °C,	12
Pot life @ 25 °C, hours	4

Note:

Temperature and thickness of application affect dry time. Temperatures under 10 °C will result in a substantially longer cure time. Temperatures over 27 °C will result in a shorter cure time. The thicker the application, the longer the cure time.

GENERAL INFORMATION

This product is not recommended for use in pure oxygen and/or oxygen rich systems and should not be selected as a sealant for chlorine or other strong oxidizing materials

For safe handling information on this product, consult the Material Safety Data Sheet (MSDS).

Directions for use

Surface Preparation:

LOCTITE® 7214™ can be applied to any clean, dry surface. Recommended methods of cleaning are as follows:

1. Remove all paint films, laitance, and unbonded particles, preferably by sandblasting.
2. Remove all oil, grease, dirt, wax or other contaminants by dissolving with a waterbased cleaner/degreaser.
3. Flush thoroughly with clean water and allow to dry.
4. After cleaning, all loose particles must be removed by brushing, air hosing or similar method.

Mixing:

1. Mechanically mix the resin using a suitable mixing blade, until it is homogenous.
2. Pour the hardener into the base component container. Mechanically mix (using same mixer blade), scraping material from the sides and bottom of the can. Mix thoroughly until uniform, approximately 3 minutes.
3. NO THINNERS MAY BE ADDED.

Application Method:

LOCTITE® 7214™ can be applied at surface temperatures between 10 °C to 37 °C. Application is not recommended when surface temperature is above or below these temperatures. The Primer can be applied by roller or brush.

1. The Primer does not require an induction period and may be applied immediately after mixing.
2. The Primer should be applied to a minimum 0.5 to 0.75 mm dry film thickness.
3. Weld seams and edges should be stripe coated prior to the complete prime coat.
4. If the anti-slip application is delayed so the surface becomes contaminated, clean the area again. Tack coat is not normally required provided the anti-slip application is made within 72 hours. After 72 hours, the primed surface must be mechanically abraded or grit-blasted prior to application of a tack coat.
5. Clean tools immediately after completing installation using an epoxy solvent such as xylene.

Loctite Material Specification^{LMS}

LMS dated April 4, 2002. Test reports for each batch are available for the indicated properties. LMS test reports include selected QC test parameters considered appropriate to specifications for customer use. Additionally, comprehensive controls are in place to assure product quality and consistency. Special customer specification requirements may be coordinated through Henkel Quality.

Storage

Store product in the unopened container in a dry location. Material removed from containers may be contaminated during use. Do not return liquid to original container. Storage information may be indicated on the product container labeling.

Optimal Storage: 8 °C to 21 °C. Storage below 8 °C or greater than 28 °C can adversely affect product properties.

Henkel cannot assume responsibility for product which has been contaminated or stored under conditions other than those recommended. If additional information is required, please contact your local Technical Service Center or Customer Service Representative.

Conversions $(^{\circ}\text{C} \times 1.8) + 32 = ^{\circ}\text{F}$ $\text{kV/mm} \times 25.4 = \text{V/mil}$ $\text{mm} / 25.4 = \text{inches}$ $\mu\text{m} / 25.4 = \text{mil}$ $\text{N} \times 0.225 = \text{lb}$ $\text{N/mm} \times 5.71 = \text{lb/in}$ $\text{N/mm}^2 \times 145 = \text{psi}$ $\text{MPa} \times 145 = \text{psi}$ $\text{N}\cdot\text{m} \times 8.851 = \text{lb}\cdot\text{in}$ $\text{N}\cdot\text{m} \times 0.738 = \text{lb}\cdot\text{ft}$ $\text{N}\cdot\text{mm} \times 0.142 = \text{oz}\cdot\text{in}$ $\text{mPa}\cdot\text{s} = \text{cP}$ **Note**

The data contained herein are furnished for information only and are believed to be reliable. We cannot assume responsibility for the results obtained by others over whose methods we have no control. It is the user's responsibility to determine suitability for the user's purpose of any production methods mentioned herein and to adopt such precautions as may be advisable for the protection of property and of persons against any hazards that may be involved in the handling and use thereof. In light of the foregoing, **Henkel Corporation specifically disclaims all warranties expressed or implied, including warranties of merchantability or fitness for a particular purpose, arising from sale or use of Henkel Corporation's products. Henkel Corporation specifically disclaims any liability for consequential or incidental damages of any kind, including lost profits.** The discussion herein of various processes or compositions is not to be interpreted as representation that they are free from domination of patents owned by others or as a license under any Henkel Corporation patents that may cover such processes or compositions. We recommend that each prospective user test his proposed application before repetitive use, using this data as a guide. This product may be covered by one or more United States or foreign patents or patent applications.

Trademark usage

Except as otherwise noted, all trademarks in this document are trademarks of Henkel Corporation in the U.S. and elsewhere. ® denotes a trademark registered in the U.S. Patent and Trademark Office.

Reference 0.0